

If your friends or associates wish copies of this booklet, have them contact the distributor.

DISTRIBUTED BY:





We have compiled this booklet as an aid to those who, because of their interest or profession, are required to do calculations. We sincerely hope that this booklet will be of genuine value to you.

Regardless of the type of calculations that you are required to do, CURTA will do them for you, faster, more accurately and with less mental strain.

Scientists, technicians, estimators, navigators, research men, contractors, appraisers, businessmen etc. etc. will find CURTA an invaluable aid in the office, in the home, in the field or wherever calculations may be required.

The CURTA Company Van Nuys, California

TABLE OF DECIMAL EQUIVALENTS

		1/6 4	.01563			3 3/6 4	, 51563
	1/32		.03125		17/32		.53125
		3/6 4	.04688	<u> </u>		35/64	. 54688
1/16			.0625	9/16			. 5625
		5/64	.07813			37/64	.57813
	3/32		.09375		19/32		. 59375
		7/64	.10938			39/64	.60938
1/8			.125	%			.625
		%4	.14063			41/64	.64063
	5/32		. 156 25		21/32		. 65625
		1 1/6 4	.17188			43/64	,67188
3/6			.1875	1 1/16			. 6875
		13/64	. 20313			4%4	.70313
	7/32		. 21875		23/32		.71875
		15/64	. 23438			47/64	.73438
1/4			. 250	3/4			.750
		17/6 4	. 26563			49/64	.76563
	9/32		. 281 25		25/32		.78125
		19/64	. 29688			5 ½ 4	.79688
5/16			. 31 25	13/16			.8125
		21/64	.32813			53/64	.82813
	1 1/32		.34375		27/32		.84375
		23/64	. 35938			5%4	.85938
%			.375	7∕8			.875
		25/64	.39063			57/64	.89063
	13/32		. 40625		29/32		.90625
		27/64	.42188			59/64	.92188
7/16			.4375	15/16			.9375
		29/64	.45313			6 1/6 4	.95313
	15/32		.46875		31/32		.96875
		31/64	.48438			63/64	.98438
1/2			.500	1			1.00000

A dwarf in size . . .

A giant in calculating efficiency

Curta is a complete pocket size calculating machine for all four arithmetical operations

Like a chronometer or a miniature camera, the CURTA calculator is a precision machine of extremely small proportions.

This amazing new construction, manufactured with up to date production-methods by CONTINA Ltd., is a masterpiece of matchless craftsmanship.

CURTA is held in one hand while operated (see figure 2, page 6) and is easily carried in a pocket or in a briefcase. Thus it fills a long felt gap in available calculating machines and complies with the wishes of a great number of users demanding a small, yet complete and reliable individual instrument.

The businessman on his trips, the professional account at his client's offices, the building contractor on the building site, the technician in the workshop, the draughtsman at his drawing board, professors and students, they all use and prefer CURTA for its handiness and accuracy.

Wherever it is inconvenient to use noisy machines or to transport heavy and bulky instruments, all the outstanding advantages of the CURTA become fully evident. In the offices of private and public enterprises, in bureaus of the administration, in banks, in booking offices, in test-laboratories, to mention a few examples, CURTA is particularly appreciated for its quiet, convenient and fast operation: Unlike other machines, CURTA, held in one hand, is always in the operator's immediate angle of vision, right above his working place (see pages 5 and 6).

Due to these remarkable features, CURTA, ever since its first appearance, has been enthusiastically received both by experts and users and has been in rapidly growing demand all over the world.

With the CURTA a miniature universal calculating machine of an entirely new design has been created. Hand operated, with "safegrip" setting knobs, visible setting dial and continuous tens transfer in the answering and the indicating dial. CURTA has the features and the perfection normally found only in more expensive modern calculating machines of far heavier weight and much larger size.

(Continued)	
٦	
Н	
RADIUS	
ARCS:	
CIRCULAR	
OF	
LENGTHS	

	1 1																					
	Length	1,7627825	1.7802358	1.7976891	1,8151424	1,8325957	1,8500490	1,8675023	1.8849556	1.9024089	1.9198622	1 0373155	1000	1.334/666	1.972221	1,9896753	2,0071286	2.0245819	2.0420352	2.0594885	2.0769418	2.0943951
(Continued)	Deg.	101	102	103	104	105	106	107	108	109	110		1011	7117	113	114	115	116	117	118	119	120
٦ =	Length	.7155850	.7330383	.7504916	.7679449	.7853982	.8028515	.8203047	.8377580	.8552113	.8726646	8901179	012200	27 /0 /00	. 9230243	.9424778	.9599311	. 9773844	.9948377	1.0122910	1.0297443	1.0471976
ARCS: RADIUS	Deg.	41	42	43	44	45	46	47	48	49	20	15	10	1 0	20	54	22	26	57	28	29	09
CIRCULAR ARC	Length	.0119264	.0122173	.0125082	.0127991	.0130900	.0133809	.0136717	.0139626	.0142535	.0145444	0148353	0151969	101010	1/14010.	.0157080	.0159989	.0162897	.0165806	.0168715	.0171624	.0174533
OF	Min.	41	42	43	44	45	46	47	48	49	20	[2	200	100	20	54	22	26	22	28	29	09
LENGTHS	Length	.0001988	.0002036	.000 2085	.0002133	.0002182	.0002230	.0002279	.0002327	.0002376	.0002424	0002473	102000	10000	.0002370	. 0002618	.0002666	.0002715	.0002763	.0002812	.0002860	.0002909
	Sec.	41	42	43	44	45	46	47	48	49	20	.53	65	100	2 :	54	22	26	57	28	29	09

40	ک ک ک	200	ى د	3 0	200	υ c 4. n	ن د د	200	31	30	29	28	27	26	25	24	23	22	21	Sec	
SERTOOO.	TERTOON.	.0001842	.0001/94	.0001745	.000169/	0001607	.0001600	.0001551	.0001503	.0001454	.0001406	.0001357	.0001309	.0001261	.0001212	.0001164	.0001115	.0001067	.0001018	Length	LENGTHS
40	39	3	3	36	0 0	24	. ω	32	32	30	29	28	27	26	25	24	23	22	21	Min.	OF
.0116355	.0113446	.0110538	.0107629	.0104720	TTRTOTO.	2068600	.0095993	.0093084	.0090175	.0087266	.0084358	.0081449	.0078540	.0075631	.0072722	.0069813	.0066904	.0063995	.0061087	Length	CIRCULAR AF
40	39	38	37							30	29	28	27	26	25	24	23	22	21	Deg.	ARCS: RADIUS
.6981317	.6806784	.6632251	.6457718	.6283185	.6108652	. 5934119	. 5759587	. 5585054	.5410521	.5235988	.5061455	.4886922	.4712389	. 4537856	. 4363323	.4188790	.4014257	.3839724	.3665191	Length	1
100	99	98	97	96	95	94	93	92	91	90	89	88	87	86	85	84	83	82	81	Deg.	(Continued)
1.7453293	1.7278760	1.7104227	92969	1.6755161	1.6580628	1.6406095	1.6231562	1.6057029	1.5882496	1.5707963	1.5533430	1.5358897	1.5184364	1.5009832	1.4835299	1.4660766	1.4486233	1.4311700	1.4137167	Length	

CURTA

has the following features in common with heavy calculating machines:

Performance

It adds, subtracts, multiplies, divides, squares, cubes, extracts, square roots. CURTA is therefore the ideal machine for invoicing, estimates, calculation of interest, currency conversions, figuring out percentages, etc.

Accuracy

CURTA is fool-proof. Automatic devices prevent errors due to wrong handling. Special stops eliminate overspeeding of the axles in fast operation.

Speed

Exceptionally fast operation is possible thanks to the small size of all moving parts, the continuous tens transfer in both dials and the one-way (clockwise) operation of the handle.

Visibility

The neatly engraved figures appear clearly on the non-glare surface of the machine. The set numbers appear automatically in the horizontal setting dial.

Quality

Only rigorously tested materials are selected for all parts of the CURTA. All parts are interchangeable and can easily be replaced.

Durability

Practically no wear can be noticed even after years of use. Tests over a long period have shown that the whole mechanism of the CURTA will stand up to millions of rotations.

Attractive appearance

Fine finish, shock-proof container.

Lower price

Thanks to its modern design and the latest manufacturing methods CURTA is sold at a much lower price than any machine of comparable performance.

Resistance to corrosion

CURTA is rust-proof and tropic-proof.

Silent action

On account of the small size of all moving parts and the use of automatic locking devices.

Convenient and easy operation

Thanks to the small weight, the easy action, the conveniently located "safe-grip" setting knobs, the clearly visible figures and the non-glare surface finish. For desk work the CURTA offers the special advantage that the operator remains in the same position for calculating as for his other work (compare the pictures on the two following pages).

NGTHS OF CIRCULAR ARCS: RADIUS = 1

	Length	1.0646508	1.0821041	1.0995574	1.1170107	1.1344640	1,1519173	1,1693706	1.1868239	1.2042772	1.2217305	1,2391838	1.2566371	1.2740904	1.2915436	1,3089969	1.3264502	1,3439035	1,3613568	1,3788101	1.3962634
	Deg.	61	62	63	64	65	99	67	89	69	70	7.1	72	73	74	7.5	76	77	78	79	80
RADIUS = 1	Length	.0174533	.0349066	.0523599	.0698132	.0872665	. 1047198	.1221730	. 1396263	.1570796	.1745329	.1919862	. 2094395	. 2268928	. 2443461	. 26 17 9 9 4	. 2792527	. 2967060	.3141593	.3316126	.3490659
CIRCULAR ARCS:	Deg.	٦	2	က	4	2	9	7	ω	თ	10	11	12	13	14	15	16	17	18	19	20
OF (Length	.0002909	.0005818	.0008727	.0011636	.0014544	.0017453	.0020362	. 00 23 27 1	.0026180	.0029089	.0031998	.0034907	.0037815	.0040724	.0043633	.0046542	.0049451	.0052360	.0055269	.0058178
LENGTHS	Min.	7	2	က	4	2	9	7	80	თ	2	11	12	13	14	15	16	17	18	19	- 20 -
	Length	.0000048	.0000097	.0000145	.0000194	.0000242	.0000291	.0000339	.0000388	.0000436	.0000485	.0000533	.0000582	.0000630	6490000.	.0000727	9240000.	.0000824	.0000873	.0000921	.0000970
	Sec.	1	101	က	4	Ŋ	9	7	80	o	10	11	12	13	14	15	16	17	18	19	20

Five-Place Logarithms (Continued)

1															
6	339	93902	439	94890	537	28	63	89	72	97727	œ	α	93078	6	9
8	33	93852	43	94841	53	95809	96284	96755	97 220	97681	813	858	99034	947	991
7	93298	93802	94300	94792	9 527 9	95761	96237	96708	97174	97635	98091	854	68686	943	987
9	32	93752	42	94743	523	57	61	96661	7.1	97589	80	84	98945	93	98
2	319	370	420	94694	518	566	614	9	708	97543	ω	œ	00686	ത	6
4	31		41	94645	513	56	9	96567	70	97497	7	œ	98886	6	6
8	9 309 5	93601	94101	94296	9 508 5	55	60	96 520	69	74	790	836	98811	925	969
2				94547	9 20 36	552	599	96473	694	740	78	8	98767	92	96
1	299	93500	400	94498	94988	95472	95952	96426	96892	97359	97818	98272	98722	99167	89607
0	29	34	39	94448		542	590	9	684	97313	77	82	98677	91	95
z	85	98	87	88	83					94	9.2	96	97	86	66




Fig. 1

COMPARE

the usual way . . .

With a heavy calculating machine:

- concentration focused alternately on TWO points
- many movements
- additional strain




Fig. 2

... and the "CURTA" way

With the CURTA-Calculator

- concentration focused on ONE point only
- no unnecessary movements
- less strain

Five-Place Logarithms (Continued)

1															
6	S	8 5673	S	9		802	8 59	89154	970	025	07	13	18	9 2376	28
œ	500	8 56 12	621	680	7 39	87967	88536	88068	89653	90200	074	127	180	92324	28 4
7	84942	8 5552	86153	86747	87332	79	8	89042	95	_	90687	9 1222	91751	9 2273	9 27 88
9	488	8 5491	609	668	727	785	842	98688	954	003	90	7	16	92221	27
2	48	85431	60	99	72	77	œ	88930	94	00	0 58	111	164	92169	268
4	8 47 57	85370	597	657	715	87737	88309	88874	89432	89982	90526	9 106 2	91593	9 21 17	9 26 3 4
က	469	8 5309	591	651	7 09	767	825	88	937	89927	04	10	15	92065	25
2	463	8 5 2 4 8	585	645	704	762	819	88762	932	89873	041	095	148	92012	253
1	457	85187	579	633	698	7 56	813	88705	926	981	036	080	143	91960	248
0	45	85126	57	63	86923	7	808	64	920	89763	03	08	13	9 19 0 8	24
z	70	7.1	72	73	74	7.5	92	77	78	7.9	80			83	

Five-Place Logarithms (Continued)

1	ı														
6	4	ш,	76268	-	-	œ	6	79865	0	\neg	18	25	31	83822	44
8	466	543	76193	693	167	8 39	909	79796	048	115	182	247	312	8 37 59	438
7	458	535	76118	989	7 59	ဆ	90	79727	041	10	81757	82413	83059	8 36 96	84323
9	450	528	76042	679	752	82	83	79657	03	70	_	$^{\circ}$	$^{\circ}$	83632	4
2	7 4 4 29	75205	7 59 67	76716	77452		œ	79588	0	0	162	228	293	83269	419
4	74351	75128	7 589 1	76641	77379	78104	78817	79518	80209	80889	_	2	$^{\circ}$	83506	4
က	427	505	75815	6 56	7 30	80	87	79449	0.1	08	149	215	280	83442	407
2	419	497	75740	649	723	964	867	79379	007	075	81425	82086	8 27 37	83378	84011
1	411	489	75664	641	715	78	98	79309	00	90	13	20	26	83315	33
0	74036	7 48 19	7 5 5 8 7	76343	77085	781	853	79239	993	061	12	19	26	83251	38
z	55	26	57	28	29	09	61	62	63	6.4				89	

Short Description





Fig. 3

The machine consists of the main body which bears at its top the revolving carriage (see fig. 3)

The main body contains the keyboard with the setting knobs protruding from slots, the adjustable white decimal markers at the base and the setting dial on top of the slots. The main axle, driven by the operating handle, passes through the center of the main body.

The carriage contains the indicating dial (white) and the answering dial (black), the decimal markers set in a groove and the clearing lever (see fig. 4). The clearing lever can be folded over when the machine is stored in its container.



Five-Place Logarithms (Continued)

															•
σ		62221	က	4	2	9	~	68034	æ	σ	90	15	23	73159	33
8	99019	62118	63144	64147	6 5 1 2 8	66087	67025	67943	68842	6 97 23	70586	71433	7 2263	7 3078	73878
7	60	62014	63043	40	6 50 31	59	69	67852	87	96	0.5	13	21	7 29 97	37
9	80	6 1 3 0 9	29	39	49	28	68	67761	98	69548	041	126	209	7 29 16	371
2	07	61805	28	38	48	580	674	69949	857	946	70329	71181	7 20 16	72835	7 36 40
4	90	6 1700	27	37	6 47 38	570	665	67578	848	937	024	109	193	72754	356
3	053	61595	263	364	46	2	9	67486	œ	9		\sim	_	72673	
2	04	61490	25	35	45	551	646	67394	830	919	70070	70927	7 1767	7 259 1	73400
1	03	61384	24	34	4	541	637	67302	821	9 10	99	80	16	7 2509	ဗ္ဗ
0	0	61278	2	က	4	2	9	67210	œ	69020	69897	70757	7 1600	72428	73239
z	40	41	42	43	44	45	46	47	48	49	20	21	22	23	54

Five-Place Logarithms (Continued)

6	41330	44560	47 567	48996	50 37 9	51720	N	54283	5 5 5 0 9	56703	57864	58995	60097
8	41162	4 4 4 4 0 4 4 59 39	47422	48855	50243	51587	52892	54158	55388	56585	57749	58883	59988
7	40993	44248	47276	48714	Ö	51455	G	40	5 5 2 6 7	46	57634	58771	59879
9	40824	44091	47129	48 57 2	49969	51322	52634	53908	55145	56348	57519	58659	59770
2	40654	43933	46982	48430	49831	51188	52504	378	5 50 23	56229	57403	58546	29660
4	40483	43775	46835	48287	49693	5	52375	53656	54900	56110	57 287	58433	29550
က	40312	4361645179	46687	48144	49554	50920	52244	$^{\circ}$	54777	55991	717	58320	59439
2	40 140	43457	46538	48001	49415	5078E	52114	53403	54654	55871	57054	58206	29329
7	39967	43297	46389	47857	49276	50651	51983	53275	4531	5751	37	8092	59218
0	39794	43136	46240	47712	49136	50515	51851	53148	54407	5 56 30	568 20	57978	29106
z	25	27	29	30	31	32	33	34	35	36	37	38	39

The handling of the machine is similar to that of ordinary large machines, except that it is held in one hand, preferably in the left, with thumb and forefinger gripping the knurled edge of the carriage. The carriage, when lifted, can easily be rotated in either direction within the number of positions of the indicating dial; it is correctly fixed by stops, each of which is determined by the position indicator arrow being even with one of the numbers on the lower edge of the carriage.

The setting of numbers (for example the terms of addition, one of the two multiplication factors, or the divisor) is done with the knobs projecting from the slots. Their zero position is at the top of the slots. To set a determined figure, the corresponding setting knob is moved down until the desired figure appears on the setting dial. The number set can thus be readily checked.

The operating handle is provided with a distinctly felt stop which enables the operator to count each turn. With a gentle pull, respectively pressure, it can be brought into its upper or back into its lower positon, this latter serving for addition and multiplication, whereas the upper is for subtraction and division. In both cases the handle is turned in the same clockwise direction. A safety device prevents it from being turned backwards.

The indicating dial (white dial) counts the turns of the handle and indicates the number of items of an addition, the multiplier of a multiplication, the quotient of a division and the root when extracting square-roots.

The white dial will register the number of turns of the handle in the place corresponding to the number on the carriage edge indicated by the position indicator arrow. The answering dial (black dial) shows the result of additions, subtractions and multiplications and in division the dividend or remainder (according to the method of division selected).

The tens transfer mechanism in both these dials saves considerable time for many operations by reducing the number of turns of the handle (viz. in shortcut-multiplication).

Among other advantages it permits the addition of multipliers which is important in cubing and percentage calculations.

The answering and the indicating dial are cleared with the **clearing lever** (see figs. 3 and 4.) It can be turned in both directions; two stops are provided between the black and the white dial. With one full turn in either direction both dials are cleared; however each dial can be cleared separately by merely sliding the clearing lever over it from one stop to the other.

Five-Place Logarithms


6	5424	743 555 059	ကက	TH (1)	285	t m	2015	984	840 620
_	6	2 037			2528		932	<u>س</u>	<u>ო</u>
ω	90309	03342 07188 10721	13988 17026		25042		33846	579	765 944
7	84510	02938 06819 10380	36	19590	24797	29447	31597	30	37475 39270
ဖ	77815	02531 06446 10037	ი გ		24551	O	31387	4	\circ
2	69897	02119 06070 09691	303 613		24304		31175	2	M M
4	60206	01703 05690 09342	$\frac{27}{58}$	875	24055	878	30963	35025	36922 38739
က	47712	01284 05308 08991	238 553		23805		307 50	483	573 356
2	30 103	00860 04922 08636	$\frac{205}{522}$	18	23553	33	30535	34635	36549 38382
П	00000	00432 04532 08279	11727 14922	17898	23300	28 10 3	30320	34439	36361 38202
		00000 04139 07918	33	17609	23045	27875	30 10 3	34242	36173 38021
z	0	10	13	15	17	13	20	22	23

Powers and Roots (Continued)

n	n²	n ³	√n	³√ <u>n</u>
7 3 7 2 7 3 7 4 7 5	5184 5329 5476	357911 373248 389017 405224 421875	8.4261498 8.4852814 8.5440037 8.6023253 8.6602540	4.1408177 4.1601676 4.1793392 4.1983365 4.2171633
76 77 78 79 80	5929 6084 6241	438976 456533 474552 493039 512000	8.7177979 8.7749644 8.8317609 8.8881944 8.9442719	4.2358236 4.2543209 4.2726587 4.2908404 4.3088694
8 1 8 2 8 3 8 4 8 5	6889 7056	531441 551368 571787 592704 614125	9.0000000 9.0553851 9.1104336 9.1651514 9.2195445	4.3267487 4.3444815 4.3620707 4.3795191 4.3968297
86 87 88 89	1	636056 658503 681472 704969 729000	9.2736185 9.3273791 9.3808315 9.4339811 9.4868330	4.4140050 4.4310476 4.4479602 4.4647451 4.4814047
9 1 9 2 9 3 9 4 9 5	8 46 4 86 49 88 36	7 53571 778688 804357 8 30584 8 57 37 5	9.5393920 9.5916630 9.6436508 9.6953597 9.7467943	4.4979414 4.5143574 4.5306549 4.5468359 4.5629026
96 97 98 99 100	9216 9409 9604 9801 10000	884736 912673 941192 970299 1000000	9.7979590 9.8488578 9.8994949 9.9498744 10.0000000	4.5788570 4.5947009 4.6104363 4.6260650 4.6415888

The reversing lever at the back of the machine acts on the indicating dial. This latter will operate in opposite sense to the answering dial when the reversing lever is brought into its lower position.

Calculating example. The numbers visible in figs. 3 and 4 illustrate the multiplication:



Back view of the machine

11

Powers and Roots (Continued)

		Powe rs	and Ro	oots (Conti	nued)
645432 X 63992. The multiplicand appears in	n	n²	n³	$\sqrt{\frac{1}{n}}$	$\sqrt[3]{n}$
the setting dial (see fig. 3), the multiplier in the white dial and the product in the black dial (see fig. 4).	36 37 38	1296 1369 1444	466 56 506 53 5487 2	6.0000000 6.0827625 6.1644140	3.3019272 3.3322219 3.3619754
The total time required for this operation, including setting, is approx. 15 seconds when	39 40	1521 1600	59319 64000	6.2449980 6.3245553	3.3912114 3.4199519
operating with 29 turns. In shortcut-multi-	41	1681	68921	6.4031242	3.4482172
plication, which is made possible by the tens	42	1764	7 4088	6.4807407	3.4760266
transfer mechanism, only 13 turns are neces-	43	1849	79507 85184	6.5574385 6.6332496	3.5033981 3.5303483
sary, which corresponds to a calculating time of approx. 10 seconds.	44 45	2025	91125	6.7082039	3.5568933
of approx. 10 seconds.	40	2116	97336	6.7823300	0 5000470
In division, approximately 30 seconds in all,	46 47	2209	103823	6.8556546	3.5830479 3.6088261
	48	2304	110592	6.9282032	3.6342412
including setting, are required to ascertain a	49	2401	117649	7.0000000	3.6593057
six digit quotient.	50	2500	125000	7.0710678	3.6840315
All other operations are performed in the	51	2601	132651	7.1414284	3.7084298
shortest time by the same methods as	52	2704	140608	7.2111026	3.7325112
used currently with large universal calculat-	53	2809	148877	7.2801099	3.7562858
ing machines.	54 55	2916 3025	157464 166375	7.3484692 7.4161985	3.7797631 3.8029525
ing machines.	33	3023		7.4101303	3.6025323
	56	3136	17 56 16	7.4833148	3.8258624
	57	3249	185193	7.5498344	3.8485011
	58 59	3364	205379	7.6157731 7.6811457	3.8708766 3.8929964
S Contract of the Contract of	60	3600	216000	7.7459667	3.9148676
8					
	61	3721	226981	7.8102497	3.9364972
	6 2	3844	238328	7.8740079	3.9578916
	63	3969	250047	7.9372539	3.9790572
	6 4 6 5	4096 4225	262144 274625	8.0000000 8.0622577	4.0000000 4.0207258
The dust and shock proof container of the CURTA.	1000				
Fig. 6	66	4356	287496	8.1240384	4.0412400
1 191 0	67	4489	300763	8.1853528	4.0615481

4.0816551 4.1015659 4.1212853

8.2462113 8.3066239

8.3666003

		Powers	allu Ruuts	
n	n²	n³	$\sqrt{\overline{n}}$	3√ <u>n</u>
1	1	1	1.0000000	1.0000000
2	4	8	1.4142136	1.2599210
3	9	27	1.7320508	1.4422496
4	16	64	2.0000000	1.5874011
5	25	125	2.2360680	1.7099759
6 7 8 9	36 49 64 81 100	216 343 512 729 1000	2.4494897 2.6457513 2.8284271 3.0000000 3.1622777	1.8171206 1.9129312 2.0000000 2.0800838 2.1544347
11	121	1331	3.3166248	2. 2239801
12	144	1728	3.4641016	2. 2894285
13	169	2197	3.6055513	2. 3513347
14	196	2744	3.7416574	2. 4101423
15	225	3375	3.8729833	2. 4662121
16	256	4096	4.0000000	2.5198421
17	289	4913	4.1231056	2.5712816
18	324	5832	4.2426407	2.6207414
19	361	6859	4.3588989	2.6684016
20	400	8000	4.4721360	2.7144176
21	441	9261	4.5825757	2.7589242
22	484	10648	4.6904158	2.8020393
23	529	12167	4.7958315	2.8438670
24	576	13824	4.8989795	2.8844991
25	625	15625	5.0000000	2.9240177
26	676	17576	5.0990195	2.9624961
27	729	19683	5.1961524	3.0000000
28	784	21952	5.2915026	3.0365890
29	841	24389	5.3851648	3.0723168
30	900	27000	5.4772256	3.1072325
31	961	29791	5.5677644	3.1413807
32	1024	32768	5.6568542	3.1748021
33	1089	35937	5.7445626	3.2075343
34	1156	39304	5.8309519	3.2396118
35	1225	42875	5.9160798	3.2710663




Fig. 7

View of the stripped main assemble with the carriage above.




Fig. 8

The above illustration shows that by means of the setting knobs the setting wheels on the setting axles are brought within range of the toothed segment of the step drum whose number of teeth corresponds to the figure set. When rotating, the single central step drum acts successively on each setting wheel. The rotation of the setting wheels is transmitted through the pinions directly to the numeral wheels of the counting mechanisms. For clarity's sake the above illustration is confined to one single digit.

In the Curta, subtraction is converted to mere addition, the step drum acting automatically with its complementary teething when it is placed in its upper position. These simple construction principles result in a considerable economy of parts and are responsible for the robust design to which the Curta owes its high dependability.



Cylinder

Area of surface of cylinder = circumference multiplied by the height plus the area of both ends.

Volume of cylinder = area of base times the height or length; .7854 times square of diameter times height; 3.1416 times square of radius times height.



Circular Ring

Area of surface of circular link = 9.8696 times the mean drameter D times d.

Volume of circular link = 2.4674 times D times square of d.



Cone

Area of convex surface of cone = 1.5708 times diameter of base times slant height.

Total surface = convex surface plus .7854 times square of diameter.

Volume of cone = square of the diameter of the base multiplied by .7854 times one-third of the height.

(Note: When either the angle E or the chord c is known the other may be found from a table of sines.)

Height h of segment of a circle = $r - \sqrt{r^2 - i \sqrt{c^2 r}}$



Ring

Area of ring = area of the large circle D minus the area of the small circle d = $\frac{\pi}{4}$ (D2-d2).



Ellipse

Area of ellipse = product of long diameter D and short diameter d multiplied by .7854.



Sphere

Area of surface of sphere = square of diameter multiplied by 3.1416.

Volume of sphere = cube of the diameter multiplied by .5236; or the cube of the radius multiplied by 4.1888.

CURTA COMES IN TWO MODELS

Both machines operate on the same principle, however Model # 2 is slightly larger to give you greater capacity.

Specifications

	MODEL # 1	MODEL # 2
	8 X 6 X 11	11 X 8 X 15
Keyboard	8 columns	11 columns
Result Dial	11 columns	15 columns
Counting Dial	6 columns	8 columns
Add or Multiply to	11 places	15 places
Divide to	6 places	8 places
Diameter	2 ¹ / ₁₆ in. (53 mm)	2 ⁹ /16 in. (65 mm)
не i ght	3 % in. (85 mm)	3 ⁵ / ₈ in. (90 mm)
Weight	8 ozs. (230 g)	12½ ozs. (360 g)

Our machines give the accuracy of a desk calculator plus the portability of a slide rule.

SERVICE

curta is made entirely of high quality metals, with the same manufacturing precision as a fine watch, therefore service required is kept at a minimum. We recommend, however, that once every two years, machines be sent in for cleaning and lubrication.

when machine does require service, you may return it to the dealer from which it was purchased. If you are some distance away, you may send it via ordinary parcel post, in its metal shock-proof container. Place the entire machine in its container into a small carton or wrap with several layers of newspaper or corrugated paper. Prices for servicing our machine are comparable to that of a watch rather than of a desk calculating machine.

WHERE AND HOW TO BUY CURTA

You may purchase our machines from the dealer or distributor whose name appears on the back of this book. Our guarantee, our terms of sale, are the same regardless of which dealer your machine is purchased from: i.e. purchase may be made on a money back guarantee. Check with your dealer regarding local taxes, cash discount, open account, time payments, if desired, etc.

(written πd); 6.2832 times the radius, or $2\pi r$; 4 times the area divided by the diameter.

Area of circle = half the diameter multiplied by half the circumference; .7854 times the square of the diameter; 3.1416 times the square of half the diameter; square of the radius multiplied by 3.1416: circumference times the diameter divided by 4

Radius of circle = half the diameter; circumference multiplied by .159155; circumference divided by 6.2832:.564189 times the square root of the area.

Diameter of circle = twice the radius; circumference divided by 3.1416; circumference multiplied by .3183; 1.128 times the square root of the area.



Sector

Area of sector of circle = length of arc 1 times half its radius r; area of whole circle divided by 360 and multiplied by the number of degrees in the angle E. Square of the radius multiplied by the number of degrees in the angle E and by .00873.




Segmen t

Area of segment of circle = area of sector minus the area of the triangle formed by the chord and the two radii = $\frac{1}{2} \ln \left[- \left[- \left(r - h \right) \right] \right]$.


MENSURATION

TRIANGLES



Area = base a times 1/2 altitude b.

OUADRILATERALS



Area = base a times altitude b.



Area = area of rectangle a plus area of triangles b, c, and d.

Area = triangle e + area of triangle f.

Area = area of rectangle a plus area of triangles b and c.



Circumference of circle = 3.1416 times the diameter, 3 1/7 times the diameter, approximately: π times the diameter

ACCESSORY

For those who wish to use Curta in the field, we have a leather shoulder strap carrying case.

> Leather case for Small Machine: No. 1 (holds calculator without metal case)

Leather case for Large Machine: No. 2 (holds calculator without metal case)

Leather case for Large Machine Only: No. S 2 (holds calculator in metal case) Also has belt loop

Every CURTA-machine is supplied with detailed operating instructions giving the elementary rules for addition, subtraction, multiplication and division.

In addition, a booklet containing the following computing examples for the CURTA calculating machines is included:

General

Division by breaking down (subtractive method)

Division by multiplying by a reciprocal The rule of three

The rule of three in a single calculation (only CURTA Model # 2)

Extended rule of three $\frac{axbxc}{dxexf}$

Calculation of roots continued multiplication axbxcxd..,etc. cubes without intermediate notes

Commerce and Industry

Checking of invoices and goods Percentage calculations

- A) Percentage increase
- B) Percentage decrease

(continued on next page)

(Continued from preceding page)

- c) Profit margin
- D) Compound percentages
- E) Profit and loss
- F) Capital and interest

Costing

Costing with simultaneous control (only CURTA Model # 2)

Calculations with nines transfer Exchange calculations
Calculations with English currency

STATISTICS

Simultaneous accumulation of a sum and a
 sum of squares (only CURTA Model # 2)
Computation of arithmetic mean and
 standard deviation

Technical and Survey Calculations

Division into a negative number (complementary number)

Calculation of co-ordinates

Determination of the amount of silver in an alloy (only CURTA Model # 2)

Determination of the angles in an acute—angled triangle, given three sides (only CURTA Model # 2)


Determination of a side of an obtuse angled triangle (given the two other sides and their included angle)

Calculation of area from co-ordinates Calculation of the distance between two points, given their co - ordinates (using Pythagoras' theorem)

Calculation of distance and azimuth (only CURTA Model # 2)

Linear interpolation


MEASURES OF VOLUME AND CAPACITY



MEASURES OF WEIGHT



MISCELLANEOUS CONVERSION FACTORS



MEASURES OF CAPACITY

10 milliliters (ml.)=	1 centiliter
10 centiliters =	1 deciliter di
10 deciliters	1 liter
10 liters	1 decaliter Di
10 decaliters=	1 hectolitere UI
10 hectoliters=	1 kiloliters Kl

The liter is equal to the volume that is occupied by 1 cubic decimeter.

MEASURES OF WEIGHT

10 milligrams (mg.)	1 centigramcg.
10 Centigrams =	l decigramde.
10 decigrams =	1 gram
10 grams =	I decagram
10 decagrams =	1 hectogram Hg.
10 hectograms =	1 kilogram Kg
1,000 kilograms=	1 ton (metric) M.T.

The gram is the weight of 1 cubic centimeter of pure distilled water at a temperature of 39.2° F.; the kilogram is the weight of 1 liter of water; the ton is the weight of 1 cubic meter of water.

METRIC CONVERSION FACTORS

MEASURES OF LENGTH

1	milli	meter	=	.03937 in.
1	centi	meter	=	.3937 in.
			=	39.37 in.
1	mete	·	=	3.28083 ft.
		(=	1.0936 yd.
		ì	=	3280.83 ft.
1	kilon	neter	=	1093.61 yd
		1	=	.62137 mi.
		,		25 4
1	inch		=	2.54 cm.
		1	=	.0254 m.
1	foot	?	=	304.8 mm.
٠	1000	{	=	.3048 m.
1	mile		=	1.609 km.

MEASURES OF AREA

1 square millimeter = 1 square centimeter = = = = = = = = = = = = = = = = = = =	155 eg in
1 square meter	10.764 sq. ft. 1.196 sq. yd.
1 are	.0247 acre 1076.4 sq. ft.
1 hectare	2.471 acres 107,640 sq. ft.
1 square kilometer	.3861 sq. mi. 247.1 acres
1 square inch	645.2 sq. mm. 6.452 sq. cm.
1 square foot	929 sq. cm. .0929 sq. m.
1 square yard	.836 sq. m.
1 acre	
1 square mile	2.5899 sq. km.

ARITHMETICAL COMPUTATION

FRACTIONS

To Reduce Common Fractions: Divide the numerator and denominator by common divisors until further reduction is impossible: $63/a_1 = 21/27 - 7/9$.

To Reduce Improper Fractions; Divide the numerator by the denominator, the quotient being a whole number and the remainder the new numerator: $43/6 = 43 + 6 = 7^{1}/6$.

To Express a Fraction as a Decimal: Divide the numerator by the denominator: % = 3.00 + 4 = 0.75.

To Reduce Complex Fractions: First express both numerator and denominator as simple fractions then multiply the upper numerator by the lower denominator for the new numerator and the lower numerator by the upper denominator

for the new denominator: $\frac{1\frac{2}{4}}{\frac{5}{6}} = \frac{\frac{7}{4}}{\frac{4}{5}} = \frac{42}{20} = \frac{2^2}{20} = \frac{2^1}{10}$.

To Reduce Fractions to a Common Denominator: Multiply the numerator of each fraction by the product of all of the denominators except its own for the new numerators and multiply all denominators together for the new common denominator: 2/3, 1/4, 3/5 = 40/80, 15/80, 35/80.

To Add Fractions: Reduce to a common denominator and add the numerators: $\frac{3}{4} + \frac{2}{3} = \frac{9}{12} + \frac{8}{12} = \frac{17}{12} = \frac{15}{12}$.

To Subtract Fractions: Reduce to a common denominator and subtract numerators: $\frac{9}{4} - \frac{2}{3} = \frac{9}{12} - \frac{8}{12} = \frac{1}{12}$.

To Multiply Fractions: Multiply the numerators for a new numerator and the denominators for a new denominator: $^{3}/_{4} \times ^{5}/_{8} = ^{15}/_{32}$.

To Divide Fractions: Invert the divisor and multiply: $^3/_4 + ^7/_8 = ^3/_4 \times ^8/_7 = ^{24}/_28 = ^6/_7$.

DECIMALS

To Express a Decimal as a Fraction: Ignore the decimal point and write the figures as the numerator of the fraction. For the denominator write a figure 1 with as many ciphers after it as there were figures following the

decimal point in the original decimal: $.0125 = \frac{125}{10000}$

To Add or Subtract Decimals: Set down the figures so that the decimal points are one above the other and proceed as in simple addition or subtraction.

To Multiply Decimals: Proceed as in simple multiplication pointing off as many decimal places in the result as there are in the multiplier and multiplicand together.

To Divide Decimals: Proceed as in simple division pointing off as many decimal places in the quotient as there are decimal places in the dividend in excess of the divisor.

RATIO AND PROPORTION

Ratio: The relation of one figure to another is termed the ratio and is sometimes expressed as a fraction with the first quantity as the numerator: the ratio of 1 to 2 = 1:2 = K.

Proportion: When ratios are equal to each other they are said to be in proportion. The ratio of 3 to 6 = 3:6 = $\frac{1}{2}$, therefore it is equal to and in proportion to the ratio of 1 to 2 and the proportion would be written 3:6 = 1:2 and read '3 is to 6 as 1 is to 2.

The first and last terms in a statement of proportion are called the extremes and the middle terms the means. A rule of proportion is that 'the product of the extremes is equal to the product of the means'. Thus, in the example given above: $3 \times 2 = 6$ and $6 \times 1 = 6$.

Mean Proportional: When the middle terms are identical this quantity is called the mean proportional of the first and last terms. In 1:2 = 2:4, 2 is the mean proportional between 1 and 4. To find the mean proportional of any two terms multiply them and extract the square root of their product; Thus the mean proportional of 2 and 50 is $\sqrt{2 \times 50} = \sqrt{100} = 10$ and therefore 2:10 = 10:50.

Formulas Based on Proportion: If proportion is expressed algebraically as a:b=c:d, then ad = bc $\frac{a}{b} = \frac{c}{d}$ a = $\frac{bc}{d}$ b = $\frac{ad}{c}$ c = $\frac{ad}{b}$, and d = $\frac{bc}{a}$: thus having given any three terms the fourth can be determined.

UNITED STATES LIQUID MEASURE			
4 gills (gi.) = 1 pint			
MEASURES OF TIME			
MISCELLANEOUS MEASURES			
12 articles			
METRIC SYSTEM			
MEASURES OF LENGTH mm. 1 millimeter mm. 10 millimeters 1 centimeter cm. 10 centimeters 1 decimeter dm. 10 decimeters 1 decimeter dm. 10 decimeters 1 meter m. 10 meters 1 decameter Dm. 10 decameters 1 decameter Dm. 10 decameters 1 decameter Dm. 10 decameters 1 hectometer Hm. m. 10 hectometers 1 kilometer Km. 10 decameter 10 dec			
100 square millimeters (mm.) = 1 square centimeter			
100 square decimeters			
MEASURES OF VOLUME			
1,000 cubic millimeters (mm³.) = 1 cubic centimeter			
UNITED STATES DRY MEASURE			
2 pints (pt.) = 1 quart			
BRITISH IMPERIAL MEASURE			
4 gills = 1 pint = 34.683 cu. in. 2 pints = 1 quart = 69.366 cu. in. 4 quarts = 2 gallon = 277.463 cu. in. 2 gallons = 1 peck = 534.926 cu. in. 4 pecks = 1 bushel = 2,219.704 cu. in. One imperial gallon contains approximately 1.2 U. S. gal.; and one imperial bushel contains approximately 1.5 U. S. bu. CIRCULAR MEASURE			
60 seconds (*) = 1 minute			
60 minutes = 1 degree 6 90 degrees = 1 quadran 6 360 degrees 1 circle 6			

UNITED STATES I IOUR MEASURE

USEFUL TABLES AND RULES

WEIGHTS AND MEASURES

MEASURES OF LENGTH

12	inches (in.)	=	1 foot ft.
3	feet	=	1 yardyd.
5 1	4 vards	=	1 rod rd.
5.280	feet	=	1 statute milemi.
6.080	feet	=	1 nautical milemi.
6	feet	=	1 fathomf.
7.92	inches	=	1 linkli.
100			1 chainch.
80	chains	=	1 statute milemi.
1	mil		
- 1	-iib		

MEASURES OF AREA

144	square inches (sq. in.)	=	1 square foot sq. ft
			1 square yard sq. yd
			1 square rod sq. rd
2721/4	square feet	=	1 square rod
			1 acre
			1 square mile sq. mi
	circular inch		
	square inch		
1			area of a circle .001 inch in diameter
1			1,273,239 circular mils
As	quare 208.71 ft. on a si	de	contains 1A., or 43,560 sq. ft.
As	quare mile, or 640 A.,	s l	known as a section.

AVOIRDUPOIS WEIGHT

437.5	grains (gr.)	=	1	ounce	oz
				pound	
2,000	pounds	=	1	short ton	Т
2,240	pounds	=	1	long ton	Т

TROY WEIGHT

24 grains (gr.)	=	1	pennyweightdwt.
20 pennyweights	=	1	ounceoz.
12 ounces (5.760 grains)	=	1	poundlb.

APOTHECARIES' (DRUGGISTS') WEIGHT

20	grains (gr.)	=	1	scruple	sc
				dram	
				ounce	
12				pound	
	The grain has the same val	ue	in	all three of these systems of weight.	

CURIC MEASURE

	C	UB	IC MEASURE
1.728	cubic inches (cu. in.)	=	1 cubic foot cu. ft.
27	cubic feet	=	1 cubic yardcu. yd.
128	cubic feet	π	1 cord (of wood)cd.
16	1/2 to 25 cubic feet	=	1 perch (of masonry) P.
100	cubic feet	=	1 register ton
	U. S. shipping ton.	3	40 cubic feet
1	U. S. shipping ton.	=	31.16 imperial bushels
	(=	32.143 U. S. bushels
		=	42 cubic feet
1	British shipping ton.	=	32.719 imperial bushels
		=	33.75 II S. buehele

BUSINESS FORMULA

DISCOUNT

To find the amount of a discount, multiply the list price, or base, by the rate of discount.

Formula: $P = B \times R$, indicating the first type of percentage problem.

To find the net price, subtract the amount of the discount from the original or list price.

Formula:

COMMISSION OR BROKERAGE

To find the commission, multiply the principal amount, or the base, by the rate of commission.

Formula:

Commission (P) = Base (B)
$$\times$$
 Rate (R), or P = B \times R

INTEREST

Interest problems employ the rules of percentage problems but include the additional factor of time.

The interest (I) is the amount of money paid for the use of money.

The **principal** (P) is the base, or the money for the use of which interest is paid.

The rate (R) is the percent charged on the basis of one year's use of the money.

The **time** (T) is the number of years, months and days over which the money is used. Note especially that 30 days are considered a month and 360 days are considered a year.

The amount (A) is the sum of the principal and the interest.

To find the interest for any given period of time, multiply the principal by the rate by the time.

Formula: $I = P \times R \times T$

To find the amount, add the interest (I) to the principal (P).

Formula: A = P + I

To find the rate when the principal, interest and time are given, divide the total interest by the time to get the amount of the interest for one year; then divide this quotient by the principal.

To find the time when the principal, interest and rate percent are given, multiply the principal by the rate to obtain the amount of interest for one year; then divide the total interest by the interest for one year.

To find the principal when the interest, the rate percent and the time are given, divide the interest by the time to get the interest for one year, then divide this by the rate.

To find the principal when the amount, rate percent and time are given, divide the given amount by the amount of \$1 for the given time at the given rate.

00.	1	.01	.02	.03	.04		90.	.07	.08	60.
332 .434	34		2	37	. 4382	.4394	.4406	.4418	.4429	44
452 . 446	46	~	1	48	49	0	ч	52	က	2
554 . 456	56	4	1	58	59	59	0	9	2	63
641 . 46	9	0,	465	99	67	67	8	69	B	70
4713 .471	-	၈	. 4726	.4732	3	74	.4750	2	.4761	9
72 . 47	_	œ	7 8	7 8	7	79	80	80	.4812	.4817
4821 48	48	2	8	83	∞	84	84	85	85	œ
4861 48	48	4	86	87	48	87	88	88	8	∞
48	0	ی ،	489	490	6	90	90	91	91	6
4918 49	σ.	0	492	492	6	92	93	93	93	9
38 . 49	0	0	494	494	9	6	. 4948	.4949	2	.4952
53 . 4	6	2	95	95	6	96	96	96	96	9
6.5 49	σ	9	96	96	6	97	97	97	97	σ
7 4 49	σ	<u>ا</u>	67	9.7	6	97	97	97	8	6
4981 498	0	0 00	4982	4983	4984	.4984	98	98	98	σ
865 . 49	9	7	98	6	တ	.4989	.4989	.4989	.4990	.4990
4999683										

Illustration

0

Д

total

φ

32

47

is

area

shaded

ကိ

= 1

1		0.5		N
. 3643 . 3849 . 4032 . 4192	. 3413	1554	.0000	.00
. 3665 . 3869 . 4049 . 4207	4 - 4	. 1591	0400	.01
. 3688 . 4068 4222	93	. 1628	7778	.02
.3708 .3907 .4082 .4236	A N (0 C	. 1664	3 (D (J I	.03
.3729 .3925 .4099 .4251	. 3264	. 2054	.0160 .0557 .0948	MEAN . 04
.3749 .3944 .4115 .4265	.3023	. 1736	.0199	.05
.3770 .3962 .4131 .4279	.3051	.1772	.0239	.06
.3790 .3980 .4147 .4292	.3078	.1443	.0675	.07
.3810 .3997 .4162 .4306	.3365	.1480	.0319	.08
. 3830 . 4015 . 4177 . 4319	. 3133	.1517	.0359	.09

Table of Areas from Mean to Distance z from for Normal Probability Distribution

COMPOUND INTEREST

Compound interest is interest which for each successive interest period is figured on a base that represents the original principal plus all the interest that has accrued in previous interest periods.

To compute compound interest, add the interest for each period to the principal before figuring the interest for the next period.

PROFIT AND LOSS PROFIT AND LOSS BASED ON COST

To find the percent gain or loss, divide the amount gained or lost by the cost.

To find the gain and the selling price when the cost and the percent gain are given, multiply the cost by the percent gain and add the result to the cost.

To find the loss and the selling price when the cost and the percent loss are given, multiply the cost by the percent loss and subtract the product from the cost.

To find the cost when the profit and the percent profit are given or to find the cost when the loss and the percent loss are given, divide the profit or loss by the percent profit or loss.

To find the cost when the selling price and the percent profit are given, divide the selling price by 1 plus the percent profit.

To find the cost when the selling price and the percent loss are given, divide the selling price by 1 minus the percent loss.

PROFIT AND LOSS BASED ON SELLING PRICE

To find the percent profit or loss, divide the amount gained or lost by the selling price.

To find the profit and the cost when the selling price and the percent profit are given, multiply the selling price by the percent profit and subtract the result from the selling price.

To find the loss and the cost when the selling price and the percent loss are given, multiply the selling price by the percent loss and add the result to the selling price.

To find the selling price when the profit and the percent profit are given, or to find the selling price when the loss and the percent loss are given, divide the profit or loss by the percent profit or loss.

To find the selling price when the cost and the percent profit are given, subtract the percent profit from 100% and divide the cost by the remainder.

To reduce percent profit on selling price to percent mark-up (percent profit on cost), divide profit on selling price by 100% minus percent profit on selling price.

To find the selling price when the cost and the percent loss are given, add the percent loss to 100% and divide the cost by this sum.

Table of t-Values Corresponding to
Various Areas in Both Tails of
t-Distribution

			More	
D =		MEAN	+t	
Degrees Confide	nce .90	.95	.98	.99
Degrees	of .10	.05	.02	.01
Freedo		al Area	in Both	Tails
1	6.314	12.706	31.821	63.657
2	2.920	4.303	6.965	9.925
3	2.353	3.182	4.541	5.841
4	2.132	2.776	3.747	4.604
5	2.015	2.571	3.365	4.032
6	1.943	2.447	3.143	3.707
7	1.895	2.365	2.998	3.499
8 9	1.860 1.833	2.306	2.896	3.355
10	1.812	2.262 2.228	2.821	3.250
				3.169
11	1.796	2.201	2.718	3.106
12	1.782	2.179	2.681	3.055
13	1.771	2.160	2.650	3.012
14	1.761	2.145	2.624	2.977
15	1.753	2.131	2.602	2.947
16	1.746 1.740	2.120	2.583	2.921
17 18	1.734	2.110 2.101	2.567 2.552	2.898 2.878
19	1.729	2.093	2.532	2.861
20	1.725	2.033	2.528	2.845
21	1.721	2.080	2.518	2.831
22	1.717	2.074	2.508	2.819
23	1.714	2.069	2.500	2.807
24	1.711	2.064	2.492	2.797
25	1.708	2.060	2.485	2.787
26	1.706	2.056	2.479	2.779
27	1.703	2.052	2.473	2.771
28 29	1.701 1.699	2.048	2.467 2.462	2.763 2.756
30	1.699	2.043	2.452	2.750
Normal	1.03/	4.042	4.43/	2.730
Distri-	1.645	1.960	2.326	2.576
bution				

Illustration: The t-value for 9 degrees of freedom corresponding to area of .05 in both tails is 2.262.

 $\sigma \overline{x}$ = standard deviation of the population being sampled

N = finite population size

n = sample size

 $\frac{N-n}{N-1}$ = finite correction factor

SAMPLING

Standard Deviation of the Sample Mean

Infinite Populations

$$s\overline{x} = \frac{s}{\sqrt{n}}$$

Finite Populations

$$s\overline{x} = \sqrt{\frac{N - n}{N - 1} \cdot \frac{sx}{\sqrt{n}}}$$

 $s_x = sample deviation$

Confidence Interval for Population

Mean Simple Large Random Somple

$$X = \pm z \overline{sx}$$

z = normal deviate

Small Sample

$$\overline{X} \pm t_{n-1} \overline{sx}$$

t = t multiple

To reduce percent loss on selling price to percent loss on cost, divide percent loss on selling price by 100% plus percent loss on selling price.

To reduce percent loss on cost to percent loss on selling price, divide percent loss on cost by 100% minus percent loss on cost.

MULTIPLICATION OF DECIMALS

To multiply decimals, proceed as in multiplication of whole numbers. But in the product, beginning at the right, point off as many places as there are in the multiplier and in the multiplicand.

To multiply a decimal by any multiple of ten, move the decimal point as many places to the right as there are zeros in the multiplier.

DIVISION OF DECIMALS

Law of division: A quotient is not changed when the dividend and divisor are both multiplied by the same number.

To divide a decimal by a whole number, proceed as with whole numbers, but place the decimal point in the quotient directly above the decimal point in the dividend.

To divide a decimal by a decimal, move the decimal point of the divisor to the right until it becomes a whole number (i.e. multiply it by ten or a multiple of ten). Next move the decimal point of the dividend the same number of places to the right, adding zeros if necessary.

Yr.	2%	21/2%	3%	31/2%	4%	41/2%	5%	51/2%	6%
21	1.02000	1.02500 1.05063	1.03000	1.03500 1.07123	1.04000 1.08160	1.04500 1.09203	1.05000 1.10250	1.05500 1.11303	1.06000 1.12360
ω	1.06121	1.07689	1.09273	1.10872	1.12486	1.14117	1.15763	1.17424	1. 19 10 2
4	1.08243	1.10381	1.12551	1.14752	1.16986	1.19252	1.21551	1.23882	1.26248
S	1.10408	1.13141	1.15927	1.18769	1.21665	1.24618	1. 276 28	1.30696	1.33823
თ	1.12616	1.15969	1.19405	1.22926	1.26532	1.30226	1.34010	1.37884	1.41852
7	1.14869	1.18869	1.22987	1. 27 228	1.31593	1.36086	1.40710	1.45468	1.50363
œ	1.17166	1.21840	1.26677	1.31681	1.36857	1.42210	1.47746	1.53469	1.59385
9	1.19509	1.24886	1.30477	1.36290	1.42331	1.48610	1.55133	1.61909	1.68948
10	1.21899	1.28009	1.34392	1.41060	1.48024	1.55297	1.62889	1.70814	1.79085
11	1.24337	1.31209	1.38423	1.45997	1.53945	1.62285	1.71034	1.80209	1.89830
12	1.26824	1.34489	1.42576	1.51107	1.60103	1.69588	1.79586	1.90121	2.01220
13	1.29361	1.37851	1.46853	1.56396	1.66507	1.77220	1.88565	2.00577	2. 13293
14	1.31948	1.41297	1.51259	1.61870	1.73168	1.85194	1.97993	2.11609	2.26090
15	1.34587	1.44830	1.55797	1.67535	1.80094	1.93528	2.07893	2.23248	2.39656
16	1.37279	1.48451	1.60471	1.73399	1.87298	2.02237	2.18287	2.35526	2.54035
17	1.40024	1.52162	1.65285	1.79468	1.94790	2.11338	2.29202	2.48480	2.69277
18	1.42825	1.55966	1.70243	1.85749	2.02582	2.20848	2.40662	2.62147	2.85434
19	1.45681	1.59865	1.75351	1.92250	2.10685	2.30786	2.52695	2.76565	3.02560
20	1.48595	1.63862	1.80611	1.98979	2.19112	2.41171	2.65330	2.91776	3.20714

COMPOUND INTEREST Showing the amount of \$1.00 at various rates

STANDARD DEVIATION

Short Form Group Data (Small Sample)

$$s_x = i \sqrt{\frac{\sum Fd^2 - \left(\frac{\sum Fd}{n}\right)^2}{N-1}}$$

Large Sample Group Data

$$s_x = i \sqrt{\frac{\sum Fd^2}{N} - \left(\frac{\sum Fd}{N}\right)^2}$$

Ungrouped Small Sample

$$\mathbf{x} = \sqrt{\frac{\sum \mathbf{x}^2}{N-1} - \frac{(\sum \mathbf{x})^2}{N(N-1)}}$$

s, = standard deviation

 $\sum = sum$

d = deviations

F = frequency

N = number of items

i = class width

X = value of item

SAMPLING

For Infinite Populations

$$\sigma \overline{\mathbf{x}} = \frac{\sigma \mathbf{x}}{\sqrt{n}}$$

For Finite Populations

$$\sigma \overline{x} = \sqrt{\frac{N-n}{N-1} \cdot \frac{\sigma x}{\sqrt{n}}}$$

MEDIAN (SHORT METHOD) GROUPED DATA

$$MED = L + \left[\frac{\frac{N}{2} - \sum P}{FMed} \right] \cdot i$$

L = lower limit of median class

 $\frac{N}{2}$ = number of frequencies ÷ 2

 $\sum F_p$ = sum of the frequencies prior to the median class

 F_{med} = frequencies in median class

i = width of the class

MODE - GROUPED DATA

$$MODE = L_1 + \left(\frac{d_1}{d_1 + d_2}\right) \cdot i$$

 L_1 = lower limit of modal class

d = absolute difference between modal class frequency and class frequency prior to it.

d₂ = absolute difference between modal class frequency and frequency subsequent to it.

Showing the interest on \$1,000 at various rates a 360-day year based on a 30-day month and SIMPLE INTEREST -

	•	משפחם	30-44½	basea on a 30-aay month and a 300-aay year.	a 200-aa1	···		
	21/2%	3%	31/2%	4%	41/2%	2%	21/%	%9
	0.069	0.083	0.097	0.111	0.125	0.139	0.153	0.167
	0.139	0.167	0.194	0.222	0.250	0.278	0.306	0.333
	0.208	0.250	0.292	0.333	0.375	0.417	0.458	0.500
	0.278	0.333	0.389	0.444	0.500	0.556	0.611	0.667
	0.347	0.417	0.486	0.556	0.625	0.694	0.764	0.833
	0.417	0.500	0.583	0.667	0.750	0.833	0.917	1.000
	2.083	2.500	2.917	3,333	3.750	4.167	4.583	5.000
	4.167	5.000	5.833	6.667	7.500	8.333	9.167	10.000
	6.250	7.500	8.750	10.000	11.250	12.500	13.750	15.000
	12.500	15.000	17.500	20.000	22.500	25.000	27.500	30.000
	25.000	30.000	35.000	40.000	45.000	50.000	55.000	60.000
J								

Additional				PRINCIPAL DISCOUNT	AL DISC	OUNT (%)			
Discounts	10	20	25	30	35	40	421/2	45	471/2
2%	. 8775	.78	.73125	.6825	.63375	. 585	. 56 06 3	. 536 25	.51188
3	.855	.76	.7125	.665	.6175	. 57	. 54625	. 5225	.49875
5-2/2	.8336	.741	.69469	. 6 48 38	.60206	. 55575	. 53259	.50944	. 48628
2	.8123	.722	.67688	.63175	. 58663	.5415	.51894	. 49638	.47381
3-3-4/2	.79199	.70395	.65995	.61596	. 57 196	. 52796	. 50 596	.48397	. 46 197
7%	.81169	.74	.69375	.6475	.60125	. 555	.53188	.50875	.48563
11/2- 21/2	.7914	.7215	.67641	.63131	. 586 22	.54113	.51858	.49603	.47348
1/2-0	.77111	.703	.65906	.61513	. 57 119	. 527 25	. 50 5 28	.48331	.46134
11/2-0-2/2	1.67933	.68542	64259	59975	55061	51/07	49 26 5	47123	44981

TABLE OF CUMULATIVE DISCOUNTS

NET PRICE

FACTORS

To find the net price, multiply the base price by the number that is shown under the principal discount and opposite the desired additional discounts. To compute the net price on a \$10.50 article with discounts of 40-20-5; under 40 and opposite 20-5 we find the number .456. The product of .456 and \$10.50 is \$4.79 net. To determine the conversion factor on any chain of cumulative discounts not in the table, multiply their complementary numbers. Example:

What is the conversion factor of 40-10-2? What is the c Solution: .60

STATISTICAL FORMULA MEASURES OF CENTRAL TENDENCY

Arithmetic Mean = Xwhen X refers to the values of the individual items, \sum (sigma) means that these values are to be summed, and n refers to the number of items.

UNGROUPED DATA

$$\overline{X} = \frac{\sum X}{n}$$

GROUPED DATA

The mean of a frequency distribution with equal class intervals:

Where

X_b = the mid point of any class

n = total frequencies

i = class width

For any class:

F = class frequency

d = unit deviation of class mid point from X_b

$$\overline{X} = X_b + \frac{\sum Fd}{n} \cdot i$$

Additional			PR	INCIPAL	PRINCIPAL DISCOUNT (%)	VT (%)		
Discounts	7 21/2	75	771/2	08	8 21/2	85	871/2	90
10-10-10-10	.18043	.16403	.14762	.13122	.11482	.09842	.08201	.06561
10-10-10-10-5	.17141	. 15582	.14024	.12466	.10908	.09349	.07791	.06233
15	. 23205	. 2125	.19125	. 17	. 14875	. 1275	. 10625	.0765
15-2½	. 22625	. 20719	.18647	. 1658	. 14503	.12431	. 10359	.07459
15-5	. 22045	. 20 188	.18169	. 1615	.13731	. 12112	.10094	.07268
15-10	. 20885	.19125	. 17213	. 153	. 13388	.11475	.09563	.06541
20	. 22	. 2	.18	. 16	. 14	. 12	.1	.08
20-5	. 209	. 19	. 17 1	. 152	. 133	. 114	.095	.076
20-10	.198	. 18	.162	. 144	.126	. 108	.09	.072
20-10-5	. 1881	.171	.1539	. 1368	.1197	.1026	.0855	.0684
25	.20625	.1875	.16875	. 15	.13125	.1125	.09375	.075
25-5	.19594	.17813	.16031	.1425	.12469	.10688	.08906	.07125
25-10	. 18563	. 16875	.15188	.135	.11813	.10125	.08438	.0675
25-10-5	. 17635	.16031	.14429	.1283	.11222	.09629	.08016	.06413

Additional		8)		PRINCI	PRINCIPAL DISCOUNT	OUNT (%)	_		
Discounts	10	20	25	30	35	40	42%	45	471/2
10	.81	.72	.675	.63	. 585	.54	.5175	.495	. 47 25
10-2%	.789	.702	.65813	.61425	.57038	. 5265	.50456	.48263	.46069
10-5	.7695	-684	.64125	.5985	.55575	.513	.49163	.47025	.44888
10 - 5 - 2%	.7 503	6999	.62522	.58354	.54186	.50018	.47933	.45849	.43765
10-7%	.74925	999.	.62438	. 58 27 5	.54113	.4995	.47869	.45788	.43706
10-7%-2%	.73052	.64935	.60877	. 56818	.5276	.48701	.46672	.44643	.42614
10-7½-5	.71179	.6237	. 59316	.55361	.51407	. 47453	. 45475	.43498	.41521
10-7½-5-2½	.69398	.6081	. 57833	. 53977	.50122	.46266	.44338	.42411	.40483
10-10	. 7 29	.648	.6075	. 567	. 526.5	486	46.57.5	4455	42525
10 - 10 - 2%	.70178	.6218	.59231	. 55283	.51334	.47385	45411	43436	.41462
10-10-5	.6925	.6156	.57713	.53865	.50018	.4617	. 44246	.42323	.40399
10-10-5-2%	.6752	.6002	. 56 27	.52518	.48768	.45016	.4314	.41264	. 39389
10-10-7½	.66433	. 5994	. 56194	. 52448	.48701	.44955	.43082	41209	.39336
10-10-7½-2½	.64772	.58442	. 54789	51136	. 47 484	.43831	. 4 200 5	.40179	.38352
10-10-7%-5	.63111	.56943	.53384	.49825	.46266	.42707	.40928	.39149	.37369
10-10-7%-5-2%	61533	. 55519	.52049	. 4858	.45109	.4164	.39905	.3817	.36435
01-01-01 29	,6561	. 5832	. 54675	.5103	.47385	.4374	.41918	.40095	. 38273

Addi tional				PRINCI	PRINCIPAL DISCOUNT	(%) TNUO:	3		
Discounts	10	20	25	30	35	40	4 21/2	45	471/2
10 - 10 - 10 - 2% $10 - 10 - 10 - 5$	6397	.56862	.53308	. 49854	. 462 . 45016	. 426 47 . 41553	.4087	39093	37316
10-10-10-5-21/2	.60771	.54018	.49344	. 47 257	. 4389	.40514	.38807	. 37138	.3545
10-10-10-10 10-10-10-10-5	. 590 5 . 56 1	. 5248	.4921	.4593	.4265	.3937	.37725	.3609	. 34445
15-2½ 15-5 15-10	765 7459 7268 6885	.68 .663 .612	.6375 .62156 .60563	.595 .5801 .5653	.5525 .53869 .52488 .49725	. 4973 . 4845 . 459	.48875 .47653 .46431 .43988	.4675 .4558 .44413 .42075	. 44625 . 43509 . 42384 . 40163
20 20-5 20-10 20-10-5	.72 .684 .648	.64 .608 .576	.6 .57 .54	.56 .532 .504	.52 .494 .468 .4446	.48 .456 .432 .4104	.46 .437 .414	.44 .418 .396	. 42
25-5	675	.57	. 5625	.525	.4875	. 45	.43125	.4125	.39375
25-10-5	. 5771	.513	.48094	.4725	.43875	. 405	.38813	.37125	.35438

Additional			PRI	NCIPAL	PRINCIPAL DISCOUNT (%)	(%) J		
Discounts	7 21/2	7.5	771%	80	8 21/2	85	871%	90
10-71/2-5	.21749	.19772	.17795	.15818	.1384	.11863	98860.	.07909
10-71/2-5-21/2	.21205		.1735	.15422	.13494	.11567	.09639	.07711
10-10	. 22275	. 2025	. 18225	.162	. 14175	.1215	.10125	.081
10-10-2%	.21718	. 19744	.17669	.15795	.13821	.11846	.09872	.07898
10-10-5	.21161	. 19238	.17314	.1539	.13466	.11543	.09619	.07695
10-10-5-2%	.20632	. 18757	.16881	.15005	.1313	.11254	.09378	.07503
10-10-7%	. 20604	.18731	.16858	.14985	.13112	.11239	.09366	.07493
10-10-7%-2%	.20089	.18263	.16437	.1461	.12784	. 10958	.09131	.07305
10-10-7%-5	.19574	.17795	.16015	.14236	.12456	. 10677	.08897	.07118
10-10-7%-5-2%	.19085	.1735	.15615	.1388	.12145	.1041	.08675	.0694
10-10-10	20040	1000	16.40.9	1450	107 50	1000	61.100	04.00
,000	. 2004	. 10440	· TOTO		. 177	COCOT.	CTTCO.	67/0.
10-10-10-22	.19546	. 17769	.15592	.14216	.12439	.10662	.08885	.07 108
10-10-10-2	.19045	.17314	.15582	.13851	.1212	.10388	.08657	.06926
10-10-10-5-2%	1.18569	18569 .16881 .15193 .13505	.15193	.13505	.11817	.10129	.08441	.08441 .06752

Additional			PR	INCIPAL	PRINCIPAL DISCOUNT	NT (%)		
Discounts	7 21/2	75	771/2	80	8 21/2	85	871/2	90
21/2	.26813	. 24375	.21938	. 195	.17063	. 14625	.12188	.0975
5	. 26 1 2 5	. 2375	.21375	. 19	. 16625	. 1425	.11875	. 095
5-2%	.25472	. 23156	. 20841	.18525	. 16 209	. 13894	.11578	.09263
	.24819	. 22563	. 20306	. 1805	.15794	. 13538	.11281	.09205
5-5-2%	.24198	.21998	.19799	.17599	.15399	.13199	.10999	.08799
7%	. 25438	.23125	.20813	. 185	.16188	.13875	.11563	.0925
7%-2%	.24802	. 22547	.20292	.18038	.15783	.13528	. 11273	.09019
1%-5	.24166	.21969	. 19772	. 17 57 5	.15378	.13181	.10984	.08788
11/2-0-2/2	. 23561	.2142	. 19278	. 17 136	.14994	.12852	.1071	.08568
10	. 2475	. 225	. 2025	. 18	. 1575	. 135	.1125	.09
10-2%	. 24 131	.21938	. 19774	. 1755	. 15356	.13163	. 10969	.08755
10-5	. 23513	. 21375	. 19238	. 171	.14963	.12825	.10688	.0855
10-5-2%	. 22925	.20841	. 18757	.16673	. 14588	.12504	. 1042	.08336
10-71/2	. 22894	.20813	.18731	. 1665	. 14569	.12488	. 10406	.08325
10-7/2-2/2	1.22321	. 20292	. 18263	1.16234	.14205	. 12175	1.10146	.08117

Addi tional				PRINCIE	PRINCIPAL DISCOUNT	COUNT (%)	(3		
Di scounts	20	521/2	5.5	211%	09	6.2%	6.5	7,19	7.0
2%	. 4875	.46313	.43875	.41438	.39	.36563	.34125	.31688	. 2925
5	.475	.45125	.4275	.40375	.38	.35625	.3325	. 30875	. 285
5-21/2	.46313	.43997	.41681	.39366	. 3705	.34734	.32419	.30103	. 27788
5-5	.45125	.42869	.40613	.38356	.361	.33844	.31588	.29331	. 27 07 5
5-5-21/2	.43997	.41797	.39597	. 37397	.35198	.32998	.30798	. 28598	. 26398
71%	.4625	43938	.41625	.39313	.37	.34688	.32375	.30063	. 2775
71/2-21/2	.45094	.42839	.40584	.3833	. 36075	.3382	.31566	. 29311	.27056
71/2-5	.43938	.41741	. 39544	.37347	.3515	.32953	. 30756	. 28559	. 26363
71/2-5-21/2	.42839	.40697	.38555	.36413	.34271	.32129	. 29987	.27845	.25703
10	.45	. 4275	.405	.3825	.36	.3375	.315	. 2925	. 27
$10 - 2\frac{1}{2}$.43875	.41681	. 39488	. 37 29 4	.351	.32906	.30713	.28519	.26325
10-5	. 4275	.40613	. 38475	.36338	.342	.32063	. 29925	. 27788	. 2565
10-5-2%	.41681	.39597	. 37 513	.35429	.33345	.31261	. 29177	. 27 093	. 25009
10-71/2	.41625	. 39544	.37463	.35381	.333	.31219	.29138	. 27 0 56	. 24975
10-71/2-21/2	40584	.38555	.36526	.34497	.32468	.30438	. 28409	. 2638	.24351

Additional				PRINCIP	AL DISC	PRINCIPAL DISCOUNT (%)			
Discounts	50	521/2	55	571/2	57½ 60 62½	6 21/2	65	671/2	70
10-71/2-5	. 39544	. 37 567	.35589	.33612	.31635	. 296 58	.27681	. 25703	. 237 26
10-71/2-5-21/2	. 38555		.347	.32772	.30844	. 28916	. 26989	.25061	. 23133
10-10	.405	. 38475	. 36 45	.34425	.324	. 30375	. 2835	. 26 3 2 5	. 243
10-10-21/2	.39488	. 37 513	.35539	. 33564	.3159	. 296 16	. 27641	. 25667	.23693
10-10-5	.38475	.36551	.34628	.32704	.3078	. 28856	. 26933	.25099	.23085
10-10-5-21/2	.37513	.35637	.33762	.31886	.30011	. 28135	. 26 259	. 24384	.22508
10-10-7%	. 37463	.35589	.33716	.31843	. 2997	. 28097	. 27224	.24351	. 22478
10-10-71/2-21/2	36 5 26	.347	.32873	.31047	.29221	. 27394	. 25568	. 23742	.21916
10-10-71/2-5	.35589	.3381	.3203	.30251	.28472	. 26692	. 24913	.23133	.21354
10-10-71/2-5-21/2 347	. 347	.32965	.3123	. 29495	. 2776	. 26025	. 2429	. 22555	. 2082
10-10-10	. 36 4 5	. 346 28	.32805	.30983	. 29 16	. 27 3 38	. 25515	.23693	. 2187
10-10-10-21/2	.35539	.33762	.31985	. 30208	. 28 431	. 26654	. 24877	. 231	. 21323
10-10-10-5	. 346 28	.32897	.31165	.29434	. 27702	. 25971	. 24239	.22508	. 20777
10-10-10-5-2% 33762	1.33762	.32074	.30386	. 28698	27009	. 28698 . 27009 . 25321	. 23633	. 21945	. 20257

Additional				PRINCI	PAL DIS	PRINCIPAL DISCOUNT (%)	(%		
Discounts	50	52%	55	571/2	09	62%	6.5	67%	7.0
10-10-10-10	.3281	.31164	. 2952	. 27884	. 2624	.24604	. 22964	.21323	.19683
10-10-10-10-5 .3116	.3116	. 29606	. 280 44	. 2649	.2493	.23374	.21815	. 20257	.18699
15	.4250	.40375	.3825	.36125	.34	.31875	. 2975	.27625	.255
15-2%	4144	.39366	.37294	.35222	.3315	.31078	. 29006	.26934	.24863
15-5	.4038	.38356	.36238	.3432	. 323	.30281	. 28262	. 26 24 4	. 24225
15-10	. 38 25	. 36 338	.34425	.32513	.3062	. 28668	.26775	.24863	. 2295
20	4.	.38	.36	.34	.32	۳.	. 28	. 26	. 24
20-5	.38	.361	.342	.323	.304	. 285	.266	. 247	. 228
20-10	.36	.342	.324	306	. 288	.27	.252	. 234	.216
20-10-5	.342	.3249	.3078	.2907	. 27 36	. 2565	. 2394	. 2233	. 2052
25	.375	.35625	.3375	.31875	e	. 28125	. 26.25	. 24375	. 225
25-5	. 2563	.33844	.32063	.30281	. 285	. 26719	. 24938	.23156	. 21375
25-10	.3375	.32063	.30375	. 28788	.27	. 25313	. 23625	. 22238	.2025
S 25-10-5	.32063	. 3046	. 28836	. 27349	. 2565	. 24047	. 22444	.21126	. 19238